CON-E-CO®

An Astec Industries Company



PROBLEM: 8yd³ maximum decumlative aggregate batcher slowed production.



PROBLEM: 5 yd³ cement batcher, double batching slowed production.



SOLUTION: 8 yd³ aggregate batcher was replaced with a 12yd³ batcher with the ability to add a 100yd³ aggregate storage bin with 3 compartments.



SOLUTION: 5yd³ cement batcher was replaced with a 10yd³ cement batcher which eliminated double batching.

SOLUTIONS

that increase production and reduce costs









237 North 13th Street - Blair, Nebraska 68008 - 402-426-4181 - Fax 402-426-4180 - www.con-e-co.com



